WO #02-60456-0 AND ALL ASSOCIATED SUBS

MO.NO Description	Crew No
02-60456-00 Capital Tracking Work Order for addition of	81
primary superheater tubing in both units.	
02-60456-01 INSTALL TEMPORARY POWER ON THE 9TH AND 14TH FLOORS OF THE BOILER FOR BOILER OVER-FIRE AIR MODS.	63
02-60456-02 TIME EXPENDED FOR GARY SPERRY TO REMOVE SOOTBLOWER CAB INTERFERENCES FOR NEW SUPERHEATER UPRATE PROJ.	57
02-60456-03 TIME EXPENDED ON 1/7/03 FOR TWO ELECTRIC SHOP APPRENTICES TO HELP GARY SPERRY.	62
02-60456-04 REMOVE INTERFERING GUTTER FOR NEW OVER FIRE AIR DUCTWORK AND REWORK IN CONDUIT.	61
02-60456-05 ASSIST WITH WIRING ON BOILER OVER-FIRE AIR PROJECT DURING U1 OUTAGE. WILL REQUIRE PRE-OUTAGE WORK.	191
02-60456-06 SEND OUT FOR REBUILD, BREAKER, 80 AMPS, 3 POLES, 600 VOLT MOLDED CASE, WESTINGHOUSE #HFB3080.	41
02-60456-07 INSTALL SCAFFOLDING AS PER DARWIN BILLS NEEDS AND INSTRUCTIONS, CONTACT DARWIN	97
02-60456-08 UNIT 1 PREOUTAGE: DISCONNECT AND REMOVE ELECTRICAL FROM N/S 9TH FL WALL BLOWERS.	57
02-60456-09 REPBUILD AND/OR REPAIR 0050.0 AMP BREAKER.	44
02-60456-10 UNIT 1 "OVER-FIRE CONTRACTOR COST TRACKER" (FOR PHIL HAILES)	81
02-60456-11 PROVIDE I&C SUPPORT IN OVER FIRE AIR PROJECT. TUBING, WIRING, INSTALLATION AND TESTING WILL BE REQUIRED FOR CAMS AIR MONITOR SYSTEMS.	191
02-60456-12 UNIT 1 "OVER-FIRE CONTRACTOR COST TRACKER" (FOR BRET KENT) FOR SAFEWAY SCAFFOLD	81
02-60456-13 PROVIDE ELECTRICAL SUPPORT OF THE OVER FIRE AIR PRODJECT. REMOVE LIGHTS ETC.	61
02-60456-14 TIME EXPENDED FOR OPERATORS ASSISTING PHIL HAILES DURING THE UNIT OUTAGE.	81
02-60456-15 RETURN PRINTED OUTPUT BOARD TO FOXBORO FOR REPAIR/REPLACEMENT.	89
02-60456-16 UNIT 1 "OVER-FIRE COST TRACKER" FOR BOILER PERFORMANCE TESTING, (AARON NISSON)	81
02-60456-17 UNIT 1 "OVER-FIRE CONTRACTOR COST TRACKER" (FOR KEN NIELSON) FOR CONTROLS INSTALLATION	81
02-60456-18 FABRICATE DOOR FRAME FOR NEW OVERFIRE AIR DOORS. (PHIL HAILES)	57
02-60456-19 UNIT 1 "OVER-FIRE CONTRACTOR COST TRACKER"	81

IP7_039422

2-25-04 pt